DPM 5075

MATERIAL SAFETY DATA SHEET

NPCA 1-1

OCT 1 4 1980

FOR COATINGS, RESINS AND RELATED MATERIALS

DATE OF PREP.	(Approved by U.S. Department of Labor "Essentially Similar" to Form OSHA-20) COMPONENT I							
		Section I						
MANUFACTURER'S NAME DEFT	CHEMICAL COATINGS		•					
STREET ADDRESS 17451 Von	Karman Ave. CITY	, STATE, AND ZIP	CODE I	vine, CA	92714			
INFORMATION TELEPHONE NO. PRODUCT CLASS EPOXY	14-549-8911 Coating ent, Gloss Yellow F			DEIDENTIFICATIO -2 Base C	a para dipendental di bandari			
	Section II — HAZ	ARDOUS	INGREDIE	NTS				
INGREDIENT		PERCENT Wt.	TLV LEL		LEÚ	VAPOR PRESSURE		
Lt.Chrome Yellow Pign	ment	30	0.05 NA		NA			

	wt.	PPM mg/M ³			1
Lt.Chrome Yellow Pigment Nethyl Ethyl Ketone N-Proply Acetate Foluene Isobutyl Acetate Methyl Cellosolve N-Butyl Alcohol Butyl Cellosolve	30 10 10 10 5 < 5 < 5 < 5 < 5	200 200 100 150 25 100 50	0.05	NA 2.0 1.7 1.0 1.27 2.28 1.45 1.1	NA 70.0 23.0 22.0 12.5 6.2 4.4 <1.0
Se	ection III — PHYSIC	ΔΙ ΠΔΤΔ	· · · · · · · · · · · · · · · · · · ·	5	

BOILING RANGE 175-340⁰F VAPOR DENSITY X HEAVIER LIGHTER. THAN A R

EVAPORATION RATE FASTER X SLOWER, THAN ETHER PERCENT VOLATILE 63.7% WEIGHT PER GALLON 10.79

Section IV — FIRE AND EXPLOSION HAZARD DATA

FLAMMABILITY CLASSIFICATION - Flammable

FLASH POINT

28⁰F Tag Open Cup ASTM D 1310

LEL

EXTINGUISHING MEDIA - Carbon dioxide, foam or dry chemicals.

UNUSUAL FIRE AND EXPLOSION HAZARDS

 Caution against application to hot surfaces and use in areas where sparks or open flames may be present.

SPECIAL FIRE FIGHTING PROCEDURES

- Do not use water stream which might spread fire. Water spray or fog can be used effectively.

Section V — HEALTH HAZARD DATA
THRESHOLD LIMIT VALUE See Section II EFFECTS OF OVEREXPOSURE
Moderate eye irritant. Possible irritation of skin by solvent. Irritation or narcosis can result from inhalation of solvent vapors.
EMERGENCY AND FIRST AID PROCEDURES Skin contact - wipe off with a rag then thorough rinsing with water and washing with mild soap and water. Eye contact - flush 10 minutes with water and consult eye physician. Inhalation - remove to fresh air.
Section VI — REACTIVITY DATA
STABILITY UNSTABLE XX STABLE CONDITIONS TO AVOID - sparks from being struck with steel object or static electricity. Avoid open flam in vicinity. Avoid exposure to heat.
HAZARDOUS POLYMERIZATION MAY OCCUR X WILL NOT OCCUR CONDITIONS TO AVOID
Section VII — SPILL OR LEAK PROCEDURES
STEPS TO BE TAKEN IN CASE MATERIAL IS BELEASED OR SPILLED.
steps to Be taken in case material is released or spilled - Absorb with oil absorbing compound or dry rags. Flush with large volume of water. Avoid sparks or open flame. WASTE DISPOSAL METHOD - Dispose of clean-up rags by wetting with water and keep in a closed container. Dispose in tightly closed container and finally sanitary
Section VIII — SPECIAL PROTECTION INFORMATION landfill.
RESPIRATORY PROTECTION Good Ventilation
VENTILATION - Use adequate ventilation using exhaust fan.
PROTECTIVE GLOVES - yes EYE PROTECTION - yes OTHER PROTECTIVE EQUIPMENT
Section IX — SPECIAL PRECAUTIONS
DOL STORAGE CATEGORY OTHER PRECAUTIONS - Avoid prolonged inhalation of vapors. - Use normal storing precautions as with any paint. Keep away from heat, spark or open flame.